



Continued rebar installation in the Large Venue in preparation for the concrete slab on grade.









Small Venue opening on first floor with quick deck delivered on site.









Grid iron being temporarily hung on the 2nd floor.

ξ







Catwalk in the Medium Venue has arrived on site.