


Ongoing structural demolition at the Large Venue.


1






View of structural demolition in Large Venue from 2nd Floor looking north.





Installation of intumescent paint the in the Medium Venue.




New CMU wall progress in the Small Venue.






New concrete pad installation for new HVAC equipment on the 4th Floor roof.



Plaster column finish mockup on the 3rd Floor.





Installation of bathroom framing in Maria's Tower.



Installation of ceiling grid and lighting in Maria's Tower.