


Large Venue structural demolition is substantially complete. Existing truss has been demolished.


1





View of Small Venue from 1st Floor.









Framing, insulation and sheetrock installation on the 3rd Floor in the Podium.

3





18th Floor insulation installation is ongoing.



Maria's Tower bathroom framing and pipe installation.