


1 Pace Plaza East Renovation - Progress Photos



10/15 Concrete pour at Large Venue mat slab, roughly 200 cubic yards.

1 Pace Plaza East Renovation - Progress Photos



West side courtyard facing structural slab demolition.

1 Pace Plaza East Renovation - Progress Photos



19th Floor roof existing water tower.



Existing rooftop mechanical equipment to be replaced.