


1 Pace Plaza East Renovation - Progress Photos



Concrete pour in balcony seating. Protections have been installed over the new stage slab in preparation for overhead structural demolition (beginning on 12/02).

1 Pace Plaza East Renovation - Progress Photos



Preparation for Small Venue CMU wall installation.
Weather wall installation at Ground Level has begun.




View of Small and Medium Venues from the courtyard.

1 Pace Plaza East Renovation - Progress Photos



Storm piping delivered to site. Installation is upcoming during week of 12/02.



CMU installation at Medium Venue perimeter walls.

1 Pace Plaza East Renovation - Progress Photos



Preparation for HVAC unit installation.



18th Floor progress.