

1 Pace Plaza East Renovation - Progress Photos



Courtyard East exterior wall enclosed, new façade wall to be installed in the future.



View from Small Venue interior towards the courtyard exterior wall.

1 Pace Plaza East Renovation - Progress Photos




Overhead structural demolition continues as well as demolition of concrete beam encasement.

1 Pace Plaza East Renovation - Progress Photos



Demolition of concrete encasement on structural steel continues.



Structural steel demolition hot work.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower Perimeter Heat Pump Unit Installation
Mockup



Concrete Stair Mockup in the Podium

1 Pace Plaza East Renovation - Progress Photos



Board of Trustee Walkthrough – December 10, 2024

