




# 1 Pace Plaza East Renovation - Progress Photos



New structural work is ongoing in the Large Venue.



# 1 Pace Plaza East Renovation - Progress Photos



Installation of engineering trades, masonry, and window film is ongoing in the podium.



# 1 Pace Plaza East Renovation - Progress Photos



Installation of mechanical risers is ongoing throughout the Podium.



# 1 Pace Plaza East Renovation - Progress Photos



Interior carpentry work is ongoing in Maria's Tower



Electrical rough-in work is ongoing throughout.