



1 Pace Plaza East Renovation - Progress Photos



Ongoing structural work in Schimmel Theater.

1 Pace Plaza East Renovation - Progress Photos




Large Venue audience concrete scope.



Large Venue decking installation.

1 Pace Plaza East Renovation - Progress Photos



Large Venue audience concrete scope scaffolding and formwork is ongoing.

1 Pace Plaza East Renovation - Progress Photos



New concrete finish mock-ups on site for the project team review.



Existing concrete finish mock up for review.