




1 Pace Plaza East Renovation - Progress Photos




MEP overhead hanger work is ongoing in small venue and large dance rehearsal.

1 Pace Plaza East Renovation - Progress Photos




Bathroom rough in ongoing on 2nd floor.

1 Pace Plaza East Renovation - Progress Photos



Wall framing perimeter insulation detail ongoing throughout the Podium.

1 Pace Plaza East Renovation - Progress Photos



Maria's Tower framing dorm room mockup was reviewed week of 03/04.